



Bathtub systems

Bath Systems with winches are used in the largest plants where quality paint enforces the use of multiple washing zones. What it is infeasible or expensive for manual powder coating plants. Bath Systems in order to improve the quality can be combined with ultrasonic bath.

Systems for the preparation of aluminum **QUALICOAT** system consists of up to 6 or more baths. The basic system consists of a bathtub with a minimum of 2 baths, one with mulled chemical degreasing-consuming, and the other for rinsing water network.

Photos

